

Tree Removal Report  
1201 San Antonio Avenue (1<sup>st</sup> side)

Date: December 9, 2014

To: Bob Huan, Public Works Director  
950 West Mall Square, Room 110  
Alameda, CA 94501

Subject: Tree Removal

Location: 1201 San Antonio Avenue

Species: Robinia psuedoacacia – Black Locust

---

Recommendation: Removal – Hazardous Tree

Summary:

The tree has root rot and has lost 50% of the anchor roots and is creating a hazardous condition and requires its immediate removal for the safety of the general public or to prevent significant damage to property. There is an urgent safety threat. The tree was inspected on December 9, 2014.

Photos:



Prepared by:

Jesse Barajas, Public Works Superintendent  
WCISA Certified Arborist # 4394A  
Qualified Applicator/ DPR # 91794

1616 Fortmann Way  
Alameda, CA 94501  
Phone (510) 747-7924, Fax (510) 521-8762  
E-mail: [jbarajas@ci.alameda.ca.us](mailto:jbarajas@ci.alameda.ca.us)